CAUSAL FACTOR: Lost Directional Control

ROADSIDE DEPARTURE: Left

General	Accident	Information
O CHOIGH	ACCIACIT	minomianom

Date: 2-2-93 Weather: Rain

Time: 2235 Surface Condition: Wet

Accident Type: Control/Traction Loss Lighting: None

Accident Severity: 3 (A) Land Use: Urban

Driver/Occupant Information Vehicle Information

Driver Age: 23 **Year:** 1992

Driver Sex: Female Vehicle Make: Toyota

Impairment: None Vehicle Model: MR-2

Familiarity

with Road: Yes ABS: No

No. of Occupants: No

Roadway Information

Trafficway Type Alignment: Straight (Median): Not divided

No. of Lanes: 2 Speed Limit: 89 km/h

Cluster Variables

GV14: 01 No avoidance actions

GV64: 01 Going straight

G V65: 05 This vehicle loss of control due to poor road conditions


GV66: 0 No avoidance maneuver

GV67: 0 No avoidance maneuver

CAUSAL FACTOR: Lost Directional Control

ROADSIDE DEPARTURE: Left

The subject vehicle was proceeding along a dark, two-lane urban roadway with no streetlights. The vehicle hit a patch of water and proceeded to hydroplane. The driver was unable to control the vehicle and exited the roadway on the left side. The vehicle impacted the left guardrail and rebounded back to the right lane.



Scale: 1/500

Vehicle Dynamic Scenario

